



Tech Info Library

Apple II High-Speed SCSI Card: SCSI Reset Line (11/96)

Revised: 11/21/96
Security: Everyone

Apple II High-Speed SCSI Card: SCSI Reset Line (11/96)

=====

Article Created: 19 March 1991
Article Reviewed/Updated: 15 November 1996

TOPIC -----

Does the new Apple II High-Speed SCSI Card use the SCSI Reset line as the older Rev C card? I have a series of hard drives that have the reset line is cut in the cable and need to know if they will function with the high-speed card, or will the cable have to be replaced.

DISCUSSION -----

The Apple II High-Speed SCSI Card pin assignments are identical to the older Apple II SCSI Interface card.

The newer card still uses the SCSI Reset Line. You may need to use a special cable or, in the case of some third-party hard drives, make the appropriate DIP switch selections.

Article Change History:
15 November 1996 - Reviewed for technical accuracy, revised formatting.

Copyright 1991-96, Apple Computer, Inc.

Tech Info Library Article Number:7588